Go!Control

HOW TO CALIBRATE THE SCREEN

Calibrating The Screen

- If you find the touchscreen display buttons are not responding properly, use the **Display Calibration** option to reset the display.

- To calibrate the display, use the following steps…

Calibrating The Screen

1. Go to **Security**, **Menu**, and then **Toolbox**.

Calibrating The Screen

2. The panel will ask you to enter your current Master Code.

Calibrating The Screen

3. Once you're in the *User Toolbox*, select **Calibrate Touchscreen** and follow the directions.